

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

JS1362
ENE
> 1
1.719 mi.
9077 ft.

MANHOLE 62967
AVENUE Z AND EAST 21 ST
BROOKLYN, NY

NY Spills S110612235
N/A

Site 2 of 2 in cluster JS

Relative:
Higher

Actual:
10 ft.

SPILLS:

Name: MANHOLE 62967
Address: AVENUE Z AND EAST 21 ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1008749 / 2011-01-19
Facility ID: 1008749
Facility Type: ER
DER Facility ID: 397299
Site ID: 442267
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2010-11-19
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2010-11-19
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-11-19
Spill Record Last Update: 2011-01-19
Spiller Name: ERT
Spiller Company: CONEDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 999
Contact Name: ERT
DEC Memo: "1/19/11 - Austin - Con Ed contained and cleaned up the spill - see eDocs for more information - Spill closed - end"
Remarks: "1 gallon of dielectric fluid was found in the earthen sumpt in the manhole."

All Materials:

Site ID: 442267
Operable Unit ID: 1192778
Operable Unit: 01
Material ID: 2188116
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: Not reported
Oxygenate: Not reported